Part Number	Description	Notes
DM/RIB/5841-078	ADS 34-1049 Interface	
DM/RIB/5841-064	ADS 34-1220 Interface	
DM/RIB/5841-072	ADS 43 Interface	
	ADS 44 Interface	
DM/RES/5342-001	ADS 48 with ADS 40.0068 Printer	
DM/RES/5829-030	ADS 49 Interface	
	Aster FR 2000 Interface	
DM/RIB/5841-085	Aster GA 715 Interface	
DM/RES/5829-085	Axiohm A470 / DH Print 471 Printer Interface	
DM/RES/5829-093	Axiohm A756 (Axiohm 7150 Emulation) Serial Printer Interface	
DM/RES/5829-083	Axiohm A756 / A758 (EscPOS) Printer Interface	
DM/RES/5829-060	Axiohm MV-150 Display Port Interface	
DM/RES/5829-075	Beetle 20 with AXIOHM 7156 Printer Interface	
DM/RES/5829-068	Beetle 20 with AXIOHM 7193 Printer Interface	
	Beetle 50 Display Port Interface	
DM/RES/5829-099	Beetle 60 with ND69 Serial Printer	
DM/RES/5829-079	Beetle XL with AXIOHM 7193 Printer Interface	
DM/RIB/5841-073	Cashmag 2000 Interface	
DM/RIB/5841-017	Casio 230ER Interface	
DM/RIB/5841-001	Casio CE 2104 Interface	
DM/RIB/5841-002	Casio CE 2200 Interface	
DM/RIB/5841-006	Casio CE 2300 Interface	
DM/RIB/5841-014	Casio CE 3115 Interface	
DM/RIB/5841-015	Casio CE 3410 Interface	
DM/RIB/5841-077	Casio CE 3700 Interface	
DM/RIB/5841-016	Casio CE 3815 Interface	
DM/RIB/5841-011	Casio CE 4500 Interface	
DM/RIB/5841-009	Casio CE 4600 Interface	
DM/RIB/5841-005	Casio CE 4700 Interface	
DM/RIB/5841-019	Casio SA 1000 Interface	
DM/RIB/5841-104	Casio SA 2000 Interface	
DM/RIB/5841-018	Casio SA 2100 Interface	
DM/RIB/5841-007	Casio TK 1200 Interface	
DM/RIB/5841-086	Casio TK 1300 Interface	
DM/RIB/5841-010	Casio TK 2100 Interface	If this ECR has a kitchen printer installed then it is not possible to install an interface
DM/RIB/5841-008	Casio TK 2200 Interface	
DM/RIB/5841-003	Casio TK 2300 Interface	
DM/RIB/5841-004	Casio TK 2700 Interface	
DM/RIB/5841-012	Casio TK 4000 Interface	
DM/RIB/5841-013	Casio TK 4300 Interface	
DM/RES/5829-107	Chartbuster Customer Display Port	
DM/REP/5858-008	Citizen CBM 231 Parallel Printer Interface	
DM/RES/5829-086	Citizen CBM 233 Serial Interface	
DM/REP/5858-003	Citizen CBM-710 Parallel Interface	
DM/RES/5829-058	Citizen CBM-710 Serial Interface	
DM/RES/5829-047	Citizen iDP 3540 / 3541 Serial Interface	
DM/REP/5858-006	Citizen iDP 3540/3541 Parallel Interface	
DM/RES/5829-055	Cummins-Allison Jetsort	

Part Number	Description	Notes
		This interface is only compatible with Datacash
D14/DE0/2000 000		Terminal fitted with an Epson TM-930II Printer. For
DM/RES/5829-023	Datacash Interface	development times on other printer options
		consult Dedicated Micros.
	DataSym 2020 Serial Slip Printer Port	
DM/RES/5829-094	Interface	
DM/RES/5829-112	DECPOS Display Port Interface	
	DIGIPOS Display Port Interface	
		Dresser Wayne has released this terminal with two printer options either an Epson or an Olivetti .
DM/RFS/5829-011	Dresser Wayne Marketeer 2000 (E 512)	The exact terminal configuration must be checked
BW#1(20/0020 011	Brosser traying mamerical 2000 (2 012)	before the interface is ordered. The interfaces are
		not interchangeable.
		Dresser Wayne has released this terminal with
		two printer options either an Epson or an Olivetti .
DM/RES/5829-013	Dresser Wayne Marketeer 2000 (PR 45)	The exact terminal configuration must be checked
		before the interface is ordered. The interfaces are
		not interchangeable.
		The American and European versions of this
		terminal have diversified and this means that it
		can no longer be regarded as a global system.
		The American version produces receipts on
DM/RES/5342-002	Dresser Wayne Nucleus RS-422 Display Port	demand and maintains an electronic journal so we
DIVI/TYLS/3342-002	Interface	have to interface to the RS-422 customer display.
		We should be able to interface to the 'rebadged'
		Olivetti printer of the European version, which has
		the pre-fix 'ISM' in the model number
		Dresser Wayne has released this terminal with
DM/DE0/5000 005	Danasan Wayana Oliyyatti lataafaaa	two printer options either an Epson or an Olivetti . The exact terminal configuration must be checked
DIM/RES/5829-035	Dresser Wayne Olivetti Interface	before the interface is ordered. The interfaces are
		not interchangeable.
		There are a range of DTS 545 terminals with a
		variety of printers and application software
DM/RIB/5841-083	DTS 545 Interface	installed in the field. Compatibility must be
21VI/1 (1D/304 1-003	D 10 040 lillellace	checked with Dedicated Micros before any lead
		times can be quoted.
DM/RIB/5841-069	Edacom 10 Interface	
	Edacom 90/10 Interface	
	Edacom 90-10/Epson TM-930II Serial	
DM/RES/5829-007	Epson BA 2728 Interface	
DM/RES/5829-115	Epson IM-300 Customer Display Port	
3111112010020 110	Interface (Com 3 Port 9-way D)	
DM/RES/5829-116	Epson IM-300 Customer Display Port	
	Interface (DM Port RJ-45)	
	Epson M-240 Slip Printer	
	Epson TM 270 Interface	
	Epson TM 270 Parallel Interface Epson TM 290 Serial Interface	
	Epson TM 300 Serial Interface	
	Epson TM 930II Granada / BK Application	
	Epson TM 930II Interface	
	Epson TM 930II Parallel Interface	
	Epson TM T-80 Interface	
DIVINICEO/0020-000	_poon rm r oo miondoo	<u> </u>

Description
DM/RES/5829-054 Epson TM-930II & TM-U950 for KIWI Norway  Epson TM-930II & TM-U950 for KIWI Norway  Epson have released an IBM Legacy System version of both the TM-H5000 & TM-6000 print which emulates an IBM M4 printer. If this Epsor printer is installed with an IBM terminal check it is being driven as an Epson EscPos Device or an IBM M4. If the printer is being driven by a IEM 4 then please contact Dedicated Micros for advice.  DM/REP/5878-003 Epson TM-T80 Parallel Interface  DM/REP/5878-006 Epson TM-T88 Parallel Interface  DM/RES/5849-003 Epson TM-T88 Serial Meggitt X-Port Interface  DM/RES/5829-014 Epson TM-U210 Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052 Fortronic F75 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RES/5829-067  DM/RES/5829-067  Epson TM-H5000 / TM-H6000 Serial Interface  Epson TM-H5000 / TM-H6000 Serial Interface  DM/REP/5878-012  DM/REP/5878-003  Epson TM-H5000 Parallel Printer Interface  DM/REP/5878-006  DM/RES/5829-063  Epson TM-T80 Parallel Interface  DM/RES/5829-063  DM/RES/5829-063  Epson TM-T80 Parallel Interface  DM/RES/5829-063  DM/RES/5829-063  Epson TM-T88 Serial Meggitt X-Port Interface  DM/RES/5829-063  DM/RES/5829-063  DM/RES/5829-052  Epson TM-U210D Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052  DM/RES/5829-052  DM/RIB/5841-087  DM/RIB/5841-084  GEC Avery S100E Interface  DM/RIB/5841-114  Celler ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RES/5829-067  Epson TM-H5000 / TM-H6000 Serial Interface  DM/REP/5878-012  Epson TM-H5000 Parallel Printer Interface  DM/REP/5878-003  Epson TM-H5000 Parallel Interface  DM/REP/5878-003  Epson TM-H5000 Parallel Interface  DM/REP/5878-003  Epson TM-T88 Parallel Interface  DM/RES/5349-003  DM/RES/5349-003  DM/RES/5829-063  DM/RES/5829-063  DM/RES/5829-063  DM/RES/5829-063  DM/RES/5829-052  DM/RES/5829-052  DM/RES/5829-052  DM/RES/5829-052  DM/RES/5829-052  DM/RES/5829-052  DM/RES/5829-052  DM/RES/5829-054  DM/RES/5829-054  DM/RES/5829-0552  DM/RES/5829-0552  DM/RES/5829-054  DM/RES/5829-0552  DM/RES/5829-0552  DM/RES/5829-0552  DM/RES/5829-054  DM/RES/5829-0552  DM/RES/5829-0552  DM/RES/5829-0552  DM/RES/5829-0552  DM/RES/5829-056  DM/RES/5829-056  DM/RES/5829-057  DM/RES/5829-057  DM/RES/5829-058  DM/RES/5829-058  DM/RES/5829-059  DM/RES/5829
DM/RES/5829-067  Epson TM-H5000 / TM-H6000 Serial Interface  Epson TM-H5000 / TM-H6000 Serial Interface  DM/REP/5878-012  Epson TM-H5000 Parallel Printer Interface  DM/REP/5878-032  Epson TM-H5000 Parallel Printer Interface  DM/REP/5878-003  Epson TM-H5000 Parallel Interface  DM/REP/5878-004  Epson TM-H5000 Parallel Interface  DM/REP/5878-005  Epson TM-T80 Parallel Interface  DM/RES/5849-003  DM/RES/5849-003  Epson TM-T88 Parallel Interface  DM/RES/5829-063  Epson TM-T88 Serial Interface  DM/RES/5829-114  Epson TM-U210 Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052  DM/RIB/5841-087  DM/RIB/5841-084  GEC Avery C110 Interface  DM/RIB/5841-114  Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/REP/5878-003 Epson TM-T80 Parallel Interface  DM/REP/5878-006 Epson TM-T88 Parallel Interface  DM/RES/5349-003 Epson TM-T88 Serial Meggitt X-Port Interface  DM/RES/5829-063 Epson TM-T88 Serial Interface  DM/RES/5829-114 Epson TM-U210 Serial Interface  DM/REP/5878-011 Epson TM-U210 Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052 Fortronic F75 Interface  DM/RIB/5841-087 Fujitsu G2220 Interface  DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/REP/5878-006 Epson TM-T88 Parallel Interface  DM/RES/5349-003 Epson TM-T88 Serial Meggitt X-Port Interface  DM/RES/5829-063 Epson TM-T88 Serial Interface  DM/RES/5829-114 Epson TM-U210 Serial Interface  DM/REP/5878-011 Epson TM-U210D Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052 Fortronic F75 Interface  DM/RIB/5841-087 Fujitsu G2220 Interface  DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RES/5349-003 Epson TM-T88 Serail Meggitt X-Port Interface  DM/RES/5829-063 Epson TM-T88 Serial Interface  DM/RES/5829-114 Epson TM-U210 Serial Interface  DM/REP/5878-011 Epson TM-U210D Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052 Fortronic F75 Interface  DM/RIB/5841-087 Fujitsu G2220 Interface  DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RES/5829-063 Epson TM-T88 Serial Interface  DM/RES/5829-114 Epson TM-U210 Serial Interface  DM/REP/5878-011 Epson TM-U210D Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052 Fortronic F75 Interface  DM/RIB/5841-087 Fujitsu G2220 Interface  DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RES/5829-114 Epson TM-U210 Serial Interface  DM/REP/5878-011 Epson TM-U210D Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052 Fortronic F75 Interface  DM/RIB/5841-087 Fujitsu G2220 Interface  DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/REP/5878-011 Epson TM-U210D Parallel Printer Interface for BILKA Denmark  DM/RES/5829-052 Fortronic F75 Interface  DM/RIB/5841-087 Fujitsu G2220 Interface  DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RES/5829-052 Fortronic F75 Interface  DM/RIB/5841-087 Fujitsu G2220 Interface  DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RIB/5841-087 Fujitsu G2220 Interface  DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RIB/5841-100 GEC Avery C110 Interface  DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RIB/5841-084 GEC Avery S100E Interface  DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
DM/RIB/5841-114 Geller ET-6600  This interface requires the installation of an additional RS-232 board. The cost of the
This interface requires the installation of an additional RS-232 board. The cost of the
additional RS-232 board. The cost of the
associated re-programming of the register is no included in the interface price.
DM/RIB/5841-120 Geller NT-2324
DM/RIB/5841-076 Geller TOWA MP2
DM/RES/5829-034  Geller TOWA MP2 Serial Interface  Geller TOWA MP2 Serial Interface  A serial version of this interface has been released. This interface will only work of Geller install an additional serial board and upgrade the ECR software to included layaway EPROM'S, additional hardware and software is not supplied by Dedicated Micros.
DM/RIB/5841-079 Geller TOWA MP3 Interface
DM/RIB/5841-094 Geller TOWA NT 1204 Interface
DM/RIB/5841-109 Geller TOWA NT 3412 Interface
The Geller-Vectron is a networked terminal and will most likely be configured to share a receipt printer and produce an electronic rather than paper journal. The Geller-Vectron has six RS-2 ports and provided that one of these ports is unoccupied then the terminal could be programmed as if a journal printer was attache provide a data source for a POS/EM system. Programming would have to be completed by a Geller Cash Register dealer and is not included the interface price.
and manage price.
DM/RES/5829-070 Gilbarco G-Site Interface

Part Number	Description	Notes
DM/RES/5829-104	Gladius Display Port Serial	
DM/RES/5829-073	Hobart Quantum Scale Interfaces	
DM/RES/5829-089	IBM 4610 Serial Security Port Interface for HOT, Finland	
DM/RES/5829-074	IBM 4610 Suremark Printer Interface	
DM/RES/5829-110	IBM 4614 SureOne for Merit Serial Port	
DM/REP/5739-002	IBM 4680/90 M2/M3/M4 Interface	
DM/REP/5739-001	IBM 4680/90 M3/M4 Printer Interface	
DM/REP/5739-003	IBM 4680/90 PSI Interface	POST Software International (PSI) have written their own printer drivers for the Model 2 version of the printer used with the IBM 468x/9x terminal
DM/RES/5829-045	IBM 4693 with NCR 7193 Printer	
	IBM 4694 with IBM Suremark 4610 Thermal	
DM/REP/5739-004	Printer	
DM/REP/5829-029	IBM 7495 Interface	
	ICL 9518-200 Integrated Interface	
	ICL 9518-200 Modular	
	ICL 9518-21 Existing BOB Interface	
	ICL 9518-21 Integrated Interface	
	ICL 9518-21 New BOB Interface	
	ICL 9518-31 Existing BOB Interface	
	ICL 9518-31 Integrated Interface	
DM/REP/5751-008	ICL 9518-31 New BOB Interface	
	ICL 9518-62 Existing BOB Interface	
	ICL 9518-62 Integrated Interface	
DM/REP/0751-009	ICL 9518-62 New BOB Interface	
	ICL 9520-100 M&S Interface	
DM/RES/5829-041	ICL 9520-150 R1&2 Interface	
DM/RES/5829-042	ICL 9520-150 R3 Interface	
DM/RES/5829-078	ICL 9530 with OPC5 & Fujitsu18151 Printer	
DM/RES/5829-031	ICL 9530 with OPC8 & Epson TM930II Serial Printer Interface	The ICL 9530 terminal is configured with an Open Periphal Connect (OPC) device, which acts the connection device between the terminal processor and the periphel devices attached to it. The functionality of this OPC device was incorporated within the enclosure of the ICL 9535 terminal. It is important that the exact of the ICL 9530 and 9535 EPoS terminals are checked so that the correct interface is ordered.
DM/RES/5829-062	ICL 9535 with FD20, FD 21 or 18151 Fujitsu Printer Interface	
DM/RES/5342-003	ICL Fujitsu TeamPOS 4000 Customer Display Port Interface	
DM/RES/5829-087	ICL Superfast Ferries Serial	
DM/RES/5829-098	ICL TEAMPOS Epson TM-H6000 Serial Printer Interface	
DM/RES/5829-095	ICL/Fujitsu (VFD) Customer Display Port Interface	
DM/RES/5829-008	Ithaca 53 Interface (IBM Proprinter/ IBM Proprinter Turbo Emulation)	
DM/RES/5829-061	Ithaca 53 Interface (NCR 2567 Emulation)	

Part Number	Description	Notes
DM/DEC/5020 000	Ithaca 53 Interface (OKI Microline 182	
DM/RES/5829-080	Emulation)	
DM/REP/5878-001	Ithaca 53 Parallel OKI Microline Emulation	The specification of the cable linking the processor to the printer should be checked as variations have been found in the field.
DM/RIB/5841-103	JCM Gold G-223 Interface	
DM/RIB/5841-102	JCM Gold G-4800 Interface	
	JCT 2002 Display Port Interface	
DM/REP/5878-005	Merit Parallel Interface (Epson TM 930II P)	
DM/RES/5829-051	Metler Toledo 8582 Counter Scale Interface	
	Metropark Car Park Ticketing Machine	
DM/RIB/5841-070	Micrelec Microbox Interface	
	NCR 2122 Integrated Interface	
	NCR 2123 Integrated Interface	
	NCR 2123 Modular Interface	
	NCR 2126 Integrated Interface	
	NCR 2126 Modular Interface	
	NCR 2127 Interface	
DM/RES/5829-009	NCR 2567 Interface	
	NCR 6417 Interface	
DM/REP/5750-001	NCR 7050 LCSIO	
	NCR 7050-2000 7150-500x Interface	
DM/REP/5877-001	NCR 7050-2000 7150-520x Interface	
DM/REP/5748-003	NCR 7052-5000 Serial	
	NCR 7053 Interface	
	NCR 7054 Interface	
DM/REP/5743-002	NCR 7058 Interface	
DM/REP/5748-004	NCR 7450 / 7150-2301-9001 Printer Interface	
DM/REP/5748-005	NCR 7450 / 7150-2301-DQT Printer Interface	
DM/REP/5748-009	NCR 7450 / NCR 7150-1105-9001 Printer	
	NCR 7450 / NCR 7192-2015 Printer	
DM/REP/5748-008	NCR 7450 / NCR 7193-1105-9001 Printer	
DM/REP/5346-001	NCR 7450 /Axiohm 7193 Printer with LV PSU	
DM/RES/5829-015	Nexor Autotank Interface	
	Nixdorf SAS Interface	This interface is not compatible with the Nixdorf 8812-100 EPoS Terminal, which has the printer linked directly to the terminal processor, unless additional equipment is purchased from SNI. This additional equipment is not included in the interface price.
	Olivetti ORS 500 Interface	
	Olivetti PR4 Interface	
DM/RIB/5841-113	Olympia CM 1668	
DM/RIB/5841-023	Omron RBS 2501 Interface	
DM/RIB/5841-027	Omron RBS 4501 Interface	
	Omron RBS 4601 Interface	
DM/RIB/5841-020	Omron RS 16 Interface	
DM/RIB/5841-093	Omron RS 18-10 Interface	
DM/RIB/5841-021	Omron RS 2410 Interface	
DM/RIB/5841-022	Omron RS 25 Interface	

Part Number	Description	Notes
DM/RIB/5841-024	Omron RS 3010 Interface	
DM/RIB/5841-044	Omron RS 3410 Interface	
	Omron RS 3510 Interface	
	Omron RS 4601 Interface	
DM/RIB/5841-029	Omron RS 5510 Interface	
DM/RIB/5841-030	Omron RS 5550 Interface	
DM/RES/5829-028	Omron RS 5555 Interface	This terminal has a number of serial printer options; the interface is only compatible with the Datac D5450 and Olivetti PR-45 printers. Any other printer will require development.
DM/RIB/5841-031	Omron RS 81 Interface	
	Panasonic 7500WS Interface	
	Panasonic JS700WS Serial Interface	
	Remanco 260 / Remanco 426 Printer	
	RHS 5410 Interface	
	RHS 5430 Interface	
	RHS 5462 Interface	
DM/RES/5829-039	RHS 6900 Interface	
DM/RES/5829-046	Ritzenhaler CLD 140 Card Entry System	
DM/RIB/5841-068	Samsung ER 2610 Interface	
DM/RIB/5841-080	Samsung ER 4600 Interface	
DM/RIB/5841-124	Samsung ER 4615 Interface	
DM/RIB/5841-081	Samsung ER 4640 Interface	
DM/RIB/5841-082	Samsung ER 4800 Interface	
	Samsung ER-5100 Interface	
	Samsung ER-650 Display Port Interface	
	Samsung SER 6540 Interface	
	Samsung SPS-1000 Serial Port Interface	
	Sanyo ECR 365 Interface	
	Sanyo ECR 375 Interface	
	Sanyo ECR 635 Interface	
	Sanyo ECR 6400 Interface	
	Sanyo ECR-338 Interface	
	Sanyo LX 845 Interface	
DM/RES/5829-053	SASI 1028 Serial Interface (Price excludes cable set)	
	Schlumberger Micromax 3000 Interface	
	Schlumberger Micromax 4000 Interface	
	Sharp ER 1772S Interface	
	Sharp ER 1910 Interface	
	Sharp ER 1911 Interface	
	Sharp ER 1920 Interface	
	Sharp ER 1921 Interface	
	Sharp ER 1970 Interface	
	Sharp ER 2396S Interface	
	Sharp ER 2905 Interface	
	Sharp ER 2908 Interface	
	Sharp ER 2910 Interface	
DM/RIB/5841-058	Sharp ER 3100 Interface	
DM/RIB/5841-096	Sharp ER 3110 Interface	
DM/RIB/5841-059	Sharp ER 3115 Interface	
DM/RIB/5841-060	Sharp ER 3250 Interface	
DM/RIB/5841-105	Sharp ER 3310 / 3311 Interface	
DM/RIB/5841-063	Sharp ER 4100 Interface	
DM/RIB/5841-119	Sharp ER-2970 / ER-2980 Interface	

Part Number	Description	Notes
DM/RIB/5841-101	Sharp ER-A170 Interface	
	Sharp ER-A250 Interface	
DM/RIB/5841-112	Sharp ER-A310 Interface	
	Sharp ER-A330 Interface	
DM/RES/5351-001	Sharp ER-A490 Serial Port Interface	
DM/RIB/5841-047	Sharp ER-A510S Interface	
DM/RIB/5841-048	Sharp ER-A550 Interface	
DM/RIB/5841-097	Sharp ER-A570 Interface	
DM/RIB/5841-125	Sharp ER-A5x0 Interface	
	Sharp ER-A610 Interface	
	Sharp ER-A650 Interface	
	Sharp ER-A650S Interface	
	Sharp ER-A750 Interface	
DM/REP/5744-004	Smart 910 / 915 Interface	
	SNI Beetle 3/60 Interface	
	Star DP 8340 / DP 8340S Serial Interface	
	Star SP 300 25-way Parallel Interface	
	Star SP 300 Centronics Parallel Interface	
	Star SP 300 Interface	
	Suntronic SM2000 Serial Interface	
	Sweda Aurora Interface	
DM/RIB/5841-108	TEC FS / MA 1450 / 1650 Interface	This interface requires that the TEC FS4511
DM/RES/5829-056	TEC FS 4511 Interface	terminal be programmed to out put data on to an Epson TM-270 Printer. Access to the programming area of the terminal's memory maybe password protected. You must ensure that the client knows all the revelant passwords before installation commences. There are also a number of TEC FS 4510 terminals installed were the interface is not compatible with this terminal.
DM/RES/5829-021	TEC FT 77 Interface	
DM/RIB/5841-043	TEC M-2300 Interface	
DM/RIB/5841-088	TEC MA 1040 Interface	
DM/RIB/5841-038	TEC MA 1100 Interface	
DM/RIB/5841-033	TEC MA 115 Interface	The interface is for the single station printer version of this register only.
DM/RIB/5841-123	TEC MA 1350 Interface	
DM/RIB/5841-039	TEC MA 1400 Interface	
	TEC MA 1600 Interface	
	TEC MA 1700 Interface	
DM/RIB/5841-042	TEC MA 1900 Interface	
	TEC MA 206 Interface	
DM/RIB/5841-035	TEC MA 230 Interface	
	TEC MA 290 Interface	
	TEC MA 305 Interface	
	TEC MA 79 Interface	
	TEC MA-516 Interface	
	TEC MA85 Interface	
DM/REP/5858-005	TEC ST-4500 with Thermal Printer	
DM/REP/5858-004	TEC ST-5500 DRJST-50R-771J R&J Printer	
	TEC ST-5501 with IBM 4610 Serial Printer	
DM/RIB/5841-045	Triumph Adler CMS 8121N Interface	

The range of Dedicated Micros RS POS interface units is being expanded all the time. Please contact you local DM representative for advice on connecting any manufacturer's equipment not currently listed in these sheets.

Part Number	Description	Notes
DM/RIB/5841-092	Uniwell U-700 Interface	
DM/RIB/5841-090	Uniwell UN 4000 "Wide Printer" Interface	
DM/RIB/5841-089	Uniwell UN 4000 MS Interface	
DM/RES/5829-048	Uniwell UX 7000 Interface	This interface requires an additional RS-232 board is installed in the register and that the software on the main PCB of the ECR is upgraded, to version 3.09 or later, to allow the output of both prices and product descriptions. Uniwell also warn that if the software is upgraded from a release 2.xx version then ECR programming details must be saved before the EPROM's are changed as the memory mapping is significantly different between software versions 2.xx and 3.xx. Dedicated Micros does not supply the RS-232 board or any required software upgrades. Costs are not inclueded in the price of the interface.
DM/RIB/5841-106	Uniwell UX-40 / UX-40F Interface	
DM/RIB/5841-091	Uniwell UX-50 Interface	

 Dedicated Micros UK
 11 Oak Street, Swinton, Manchester M27 4FL UK Tel: +44 (0) 161 727 3200 Fax: +44 (0) 161 727 3300.

 Dedicated Micros USA
 14434 Albemarle Point Place, Suite 100, Chantilly, Virginia 20151 USA Freephone: 800 864 7539 Tel: +1 703 904-7738 Fax: +1 703 904-7743.

 Dedicated Micros Europe
 Neckarstraße 15, 41836 Hückelhoven, Germany Tel: +49 243 352 580 Fax: +49 24 33 52 58 10.

Dedicated Micros Asia 16 New Industrial Road, #03-03 Hudson TechnoCentre, Singapore 536204

Tel: +65 62858982 Fax: +65 62858646.

Dedicated Micros Australia

Dedicated Micros Malta

UB 2, San Gwann Ind. Est., San Gwann, Malta Tel: +356 21483 673 Fax: +356 21449 170.

Dedicated Micros Middle East
& Africa

Africa

Tel: +971 (4) 390 1015, Fax: +971 (4) 390 8655, Mobile: +971(50) 4500 149.

